

State of Colorado  
Energy & Carbon Management Commission



Document Number:  
403823840

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:  
06/13/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:  
1 of 1 CAs from the FIR responded to on this Form  
1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10351  
Name of Operator: WAPITI OPERATING LLC  
Address: 1251 LUMPKIN RD  
City: HOUSTON State: TX Zip: 77043  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Mattorano, Michael	575-445-6704/505-652-0416	mmattorano@wapitienergy.com
Beardslee, Tom		tom.beardslee@state.co.us
Madison, Randy	575-445-6706/575-420-1120	rmadison@wapitienergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601099  
Inspection Date: 06/10/2024 FIR Submit Date: 06/11/2024 FIR Status:

Inspected Operator Information:

Company Name: WAPITI OPERATING LLC Company Number: 10351  
Address: 1251 LUMPKIN RD  
City: HOUSTON State: TX Zip: 77043

LOCATION - Location ID: 307697

Location Name: VPR C-635S66W Number: 5SENE County: LAS ANIMAS  
Qtrqtr: SENE Sec: 5 Twp: 35S Range: 66W Meridian: 6  
Latitude: 37.028410 Longitude: -104.795020

FACILITY - API Number: 05-071-00 Facility ID: 89235

Facility Name: VPR C Number: 4  
Qtrqtr: SENE Sec: 5 Twp: 35S Range: 66W Meridian: 6  
Latitude: 37.028410 Longitude: -104.795020

CORRECTIVE ACTIONS:

1 CA# 195791

Corrective Action: Comply with Rule 903.d.(2)  
Immediately cease venting.  
Submit form 4 to report gas venting. Date: 06/13/2024

Response: CA COMPLETED Date of Completion: 06/10/2024

When notified that the drip was venting to atmosphere it was closed immediately. It was determined it had been knocked open by wildlife. The valve was closed and plug installed to prevent this from happening in the future.

Operator Comment: Due to the fact this is a low pressure line and only 1 well on that lateral I estimate the volume to be 24 mcf. The volume lose did not show up on any SCADA readings. See attached Gas Analysis

ECMC Decision: \_\_\_\_\_

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Thanks for the notification that this drip was venting.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy L. Madison

Signed: \_\_\_\_\_

Title: HSE & Reg. Specialist, Sr

Date: 6/13/2024 10:14:42 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403823909	Gas Analysis
-----------	--------------

Total Attach: 1 Files