

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403834654

Date Received:

06/25/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Tyranny Bergin

Phone

970-313-5547

Email

EHSCOGCCInspections@pdce.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 694100349

Inspection Date: 04/25/2024

FIR Submit Date: 05/02/2024

FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 329853

Location Name: Sanford Number: 21-29 Pad County: _____

Qtrqtr: NENW Sec: 29 Twp: 5N Range: 66W Meridian: 6

Latitude: 40.375420 Longitude: -104.805000

FACILITY - API Number: 05-123-00 Facility ID: 329853

Facility Name: Sanford Number: 21-29 Pad

Qtrqtr: NENW Sec: 29 Twp: 5N Range: 66W Meridian: 6

Latitude: 40.375420 Longitude: -104.805000

CORRECTIVE ACTIONS:

1 CA# 194860

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).

Date: 05/16/2024

Response: CA COMPLETED

Date of Completion: 06/13/2024

Operator
Comment:

Berm has been repaired. Soil has been cleaned up and fittings tightened. CA's complete.

ECMC Decision: _____

ECMC Representative:		
----------------------	--	--

2

CA# 194861

Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)C	Date: 05/09/2024
Response:	CA COMPLETED	Date of Completion: 06/13/2024
Operator Comment:	Berm has been repaired. Soil has been cleaned up and fittings tightened. CA's complete.	
ECMC Decision:		
ECMC Representative:		

3

CA# 194862

Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)C	Date: 05/16/2024
Response:	CA COMPLETED	Date of Completion: 06/13/2024
Operator Comment:	Berm has been repaired. Soil has been cleaned up and fittings tightened. CA's complete.	
ECMC Decision:		
ECMC Representative:		

OPERATOR COMMENT AND SUBMITTAL

Comment:	Berm has been repaired. Soil has been cleaned up and fittings tightened. CA's complete.
----------	---

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name:	Tyranny Bergin	Signed:	
Title:	H&S Specialist	Date:	6/25/2024 9:07:14 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description

Total Attach: 0 Files