

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403834670

Date Received:
06/25/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Tyranny Bergin

Phone

970-313-5547

Email

EHSCOGCCInspections@pdce.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713900576

Inspection Date: 04/29/2024

FIR Submit Date: 05/01/2024

FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 470630

Location Name: ELLA-64N66W Number: 5SWNW County: _____

Qtrqtr: NENW Sec: 5 Twp: 4N Range: 66W Meridian: 6

Latitude: 40.346176 Longitude: -104.805992

FACILITY - API Number: 05-123-00 Facility ID: 470630

Facility Name: ELLA-64N66W Number: 5SWNW

Qtrqtr: NENW Sec: 5 Twp: 4N Range: 66W Meridian: 6

Latitude: 40.346176 Longitude: -104.805992

CORRECTIVE ACTIONS:

1 CA# 194822

Corrective Action: Remove equipment to comply with Rule 606.

Date: 05/31/2024

Response: CA COMPLETED

Date of Completion: 06/13/2024

Operator
Comment:

Land owner has moved farm equipment from this spot. CA complete.

ECMC Decision:

ECMC Representative:		
----------------------	--	--

2

CA# 194823

Corrective Action:

Operator shall abide by the reclamation rules to minimize surface disturbances per Rule 1002.e by reclaiming the unused area of the production pad used as storage.

Date: 11/01/2024

Response:

CA COMPLETED

Date of Completion: 06/13/2024

Operator Comment:

Area the farm equipment was located has been ripped and re-seeded. Will continue to monitor. CA complete.

ECMC Decision:

ECMC Representative:

3

CA# 194824

Corrective Action:

Repair erosion and install BMP's per Rule 1002.f.

Date: 05/06/2024

Response:

CA COMPLETED

Date of Completion: 06/13/2024

Operator Comment:

Berm has been repaired. CA complete.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

Land owner has moved farm euipment from this spot. Area the farm equipment was located has been ripped and re-seeded. Will continue to monitor. Berm has been repaired. CA's complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name:

Tyranny Bergin

Signed:

Title:

H&S Specialist

Date:

6/25/2024 9:17:58 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files