



Thunder 7502

Corrective Actions Complete

API# 05-103-08544

NWSE 29 4SW102W 6

Facility ID# 230875

Insp # 403832018

The following image shows compliance with ECMC's corrective action issued on 6/19/2024. Utah Gas Corp has removed weeds from the location, and installed stormwater erosion control BMP's to manage runoff in a way that minimizes erosion.



Picture taken on 7/2/2024



Picture taken on 7/2/2024



Picture taken on 7/3/2024



Picture taken on 7/3/2024