

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403846441

Date Received:  
07/08/2024

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

. General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000770

Inspection Date: 05/21/2024

FIR Submit Date: 05/29/2024

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 413525

Location Name: LEWIS GU Number: 2 County: \_\_\_\_\_

Qtrqtr: NWS Sec: 21 Twp: 35N Range: 7W Meridian: N  
W

Latitude: 37.285970 Longitude: -107.646440

FACILITY - API Number: 05-067- -00 Facility ID: 413525

Facility Name: LEWIS GU Number: 2

Qtrqtr: NWS Sec: 21 Twp: 35N Range: 7W Meridian: N  
W

Latitude: 37.285970 Longitude: -107.646440

CORRECTIVE ACTIONS:

**1**  CA# 195457

Corrective Action: Remove/treat noxious weeds on location.

Date: 06/05/2024

Response: CA COMPLETED

Date of Completion: 06/17/2024

Operator Comment: Mechanical removal of weeds (mullen)

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

2  CA# 195458

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 06/12/2024

Response: CA COMPLETED

Date of Completion: 06/17/2024

Operator Comment: bare area was reseeded and re-mulched.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

3  CA# 195459

Corrective Action: Comply with rule 1002 Install or repair required BMPs.

Date: 06/12/2024

Response: CA COMPLETED

Date of Completion: 06/17/2024

Operator Comment: bare area was reseeded and re-mulched

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action complete. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson Signed: \_\_\_\_\_

Title: Permitting Specialist I Date: 7/8/2024 7:59:00 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403846441	FIR RESOLUTION SUBMITTED
403846464	Lewis 2 CA photos

Total Attach: 2 Files