

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403846925

Date Received:

07/08/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Shorty, Priscilla

505-324-5188

pshorty@hilcorp.com

Jones, Tammy

FarmingtonRegulatoryTechs@hilcorp.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000826

Inspection Date: 06/12/2024

FIR Submit Date: 06/14/2024

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 333954

Location Name: ARGENTA 34-10-M34N10W Number: 33NWNE County: _____

Qtrqtr: NWNE Sec: 33 Twp: 34N Range: 10W Meridian: M

Latitude: 37.151897 Longitude: -107.935170

FACILITY - API Number: 05-067-00 Facility ID: 333954

Facility Name: ARGENTA 34-10-M34N10W Number: 33NWNE

Qtrqtr: NWNE Sec: 33 Twp: 34N Range: 10W Meridian: M

Latitude: 37.151897 Longitude: -107.935170

CORRECTIVE ACTIONS:

1 ☒ CA# 195921

Corrective Action: Comply with rule 606. Remove and properly store unused equipment/debris.

Date: 06/28/2024

Response: CA COMPLETED

Date of Completion: 07/08/2024

Operator
Comment:

Unused equipment and debris have been removed and disposed of properly.

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.
----------------------	--

2 CA# 195922

Corrective Action:	Maintain equipment and clean up impacted material and dispose per Rule 906 and 1002.
--------------------	--

Date: 06/18/2024

Response: CA COMPLETED

Date of Completion: 07/08/2024

Operator Comment:	Impacted soil has been removed and disposed of properly.
-------------------	--

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.
----------------------	--

3 CA# 195923

Corrective Action:	Comply with rule 1002 Install or repair required BMPs.
--------------------	--

Date:

Response: CA COMPLETED

Date of Completion: 07/08/2024

Operator Comment:	Storm water issues have been addressed.
-------------------	---

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.
----------------------	--

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached resolved photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tammy Jones

Signed:

Title: Ops/Regulatory Tech

Date: 7/8/2024 10:39:25 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403846925	FIR RESOLUTION SUBMITTED
403846940	Resolved Photos

Total Attach: 2 Files