

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403853644

Date Received:

07/15/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 992 S 4TH AVE SUITE 100-461

City: BRIGHTON State: CO Zip: 80601

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Harms, Jason

Jason@strachanexploration.com

BEAR STACY L

stacy@strachanexploration.com

Enforcement

dnr_ecmcenforcement@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601179

Inspection Date: 06/26/2024

FIR Submit Date: 06/27/2024

FIR Status: _____

Inspected Operator Information:

Company Name: STRACHAN EXPLORATION INC

Company Number: 83130

Address: 992 S 4TH AVE SUITE 100-461

City: BRIGHTON State: CO Zip: 80601

LOCATION - Location ID: 321213

Location Name: BOURNE-622S48W

Number: 30SENW

County: BENT

Qtrqtr: SENW

Sec: 30

Twp: 22S

Range: 48W

Meridian: 6

Latitude: 38.108569

Longitude: -102.844847

FACILITY - API Number: 05-011-

-00

Facility ID: 206286

Facility Name: BOURNE

Number: 1

Qtrqtr: SENW

Sec: 30

Twp: 22S

Range: 48W

Meridian: 6

Latitude: 38.108569

Longitude: -102.844847

CORRECTIVE ACTIONS:

1 CA# 196188

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 06/27/2024

Response: CA COMPLETED

Date of Completion: 07/24/2024

Operator Comment: Filed a form 27 to remove the tank which is NOT in use. Approved 7/12 and will be removed as quickly as we can get equipment. Samples will be obtained under the tank per F27 specs. We will not rebuild the berm

ECMC Decision: _____

ECMC
Representative:

2 CA# 196189

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: _____

Response: CA COMPLETED

Date of Completion: 06/28/2024

Operator
Comment: Disconnected separator, Dug up stained earth into 6ea 5 gal buckets and stored in secondary containment. Replumbed flow line around the separator position subsurface. form 19 was submitted but will request it be pulled due to volume being under the threshold.

ECMC Decision: _____

ECMC
Representative:

3 CA# 196190

Corrective Action: Comply with Rule 606.

Date: _____

Response: CA COMPLETED

Date of Completion: 06/28/2024

Operator
Comment: Riser near wellhead has been capped

ECMC Decision: _____

ECMC
Representative:

4 CA# 196191

Corrective Action: Comply with 606.

Date: _____

Response: CA COMPLETED

Date of Completion: 07/24/2024

Operator
Comment: Weeds within the bounds of the normal usage area have been pulled. The area around the perimeter will be mowed this week when equipment is on location

ECMC Decision: _____

ECMC
Representative:

5 CA# 196192

Corrective Action: Install sign to comply with Rule 605.e.

Date: _____

Response: CA COMPLETED

Date of Completion: 07/24/2024

Operator
Comment: New wellhead signs ordered 6/28, Expect delivery this week and will install ASA received

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

Form 27 for removal of tank and Separator were approved 7/12/24. Will finish up this week. MEOH tank will also be removed from Location when equipment is available

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Shawn Reed

Signed: _____

Title: Petroleum Consultant

Date: 7/15/2024 6:12:06 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403853649	Photo Riser
403853650	Excavated replumbed flow line

Total Attach: 2 Files