

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403805926

Date Received:

05/31/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 713900625

Inspection Date: 05/14/2024

FIR Submit Date: 05/23/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: CRESTONE PEAK RESOURCES OPERATING LLC

Company Number: 10633

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 451622

Location Name: State Challenger 5-65 2-3 Number: 3BYH County: \_\_\_\_\_

Qtrqtr: NWS Sec: 1 Twp: 5S Range: 65W Meridian: 6  
W

Latitude: 39.642569 Longitude: -104.618422

### FACILITY - API Number: 05-005- -00 Facility ID: 451622

Facility Name: State Challenger 5-65 2-3 Number: 3BYH

Qtrqtr: NWS Sec: 1 Twp: 5S Range: 65W Meridian: 6  
W

Latitude: 39.642569 Longitude: -104.618422

### CORRECTIVE ACTIONS:

1 CA# 195395

Corrective Action: Install wildlife protection equipment per Rule 608.a.

Date: 05/30/2024

Response: CA COMPLETED

Date of Completion: 05/24/2024

Operator  
Comment:

Operator has reported that rain caps have been installed on all PRVs to comply with Rule 608.a.

ECMC Decision: \_\_\_\_\_

	ECMC Representative:		
2	CA# 195396		
Corrective Action:		Maintain the wellhead cellar as to sufficiently keep out wildlife per Rule 608.a.	Date: 05/30/2024
Response:		CA COMPLETED	Date of Completion: 05/24/2024
Operator Comment:		Operator has reported that wellhead cellar has been bottomed out and maintenance ticket has been submitted to have new wellhead grating installed to comply with Rule 608.a.	
ECMC Decision:			
ECMC Representative:			

	3 CA# 195397		
Corrective Action:		Remove stained soil and clean out containment on sled per Rule 912.a.	Date: 06/23/2024
Response:		CA COMPLETED	Date of Completion: 05/24/2024
Operator Comment:		Operator has reported that the identified areas with stained soil have been appropriately cleaned and stained soil has been disposed of to comply with Rule 905.e.	
ECMC Decision:			
ECMC Representative:			

	4 CA# 195398		
Corrective Action:		Erosion along the ditch should be repaired and low spots on the production pad should be re-graded as to not pond water to comply with Rule 1002.f.	Date: 06/23/2024
Response:		CA COMPLETED	Date of Completion: 05/24/2024
Operator Comment:		Operator has reported that identified erosion along the eastern drainage ditch feeding into the sediment basin has been repaired, and additional rock check dams were installed to slow the velocity of the water flow. In addition to the repairs, a native seed mix was hand broadcasted into these areas. The Pad surface was also regraded to facilitate positive water shed towards the drainage swales. Location currently complies with Rule 1002.f.	
ECMC Decision:			
ECMC Representative:			

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	CA follow-up has been completed for this location.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Ashley Noonan	Signed: _____
Title: Sr Regulatory Analyst	Date: 5/31/2024 10:40:21 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403805926	FIR RESOLUTION SUBMITTED
403806525	Inspection Report Resolution

Total Attach: 2 Files