

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2024

Submitted Date:

07/25/2024

Document Number:

694100401**FIELD INSPECTION FORM**Loc ID 424387 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Carveth, Cole		cole.carveth@crestonepr.com	
,		Cogcc.inspections@crestonepr.com	ALL INSPECTIONS
,		Inspections@civiresources.com	All Inspections

**General Comment:**

This is an environmental inspection for Location ID 424387 Liberty 2-21 battery. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location					
Overall Good: <input type="checkbox"/>					
Emergency Contact Number:					
Comment:					
Corrective Action:				Date: _____	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:		Open excavation on site from recent spill. Impacted soils have been remeoved. Awaiting confirmation sample results. Form 19 has been submitted.			
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type					
Comment:	Orange construction fencing around the open excavation is falling down, needs to be re-secured.				
Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)C				Date: 08/08/2024
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Environmental

Spills/Releases:

Type of Spill:Estimated Spill Volume:

Comment:Open excavation due to recent spill. Surrounded by orange fencing. Awaiting confirmation soil samples. .

Corrective Action:

Date:

Reportable:GPS: LatLong

Proximity to Surface Water:Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:Owner Name:GPS :LatLong

Field Parameters:

Sample Location:Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100402	photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639547">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639547</a>