

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



Photo # 3409 From entrance to location




Photo # 3410 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



Photo # 3411 Location



Photo # 3412 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



Photo # 3413 Location



Photo # 3414 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



Photo # 3415 Location



Photo # 3416 Dead weeds/debris near wellheads & chemical tank that is causing a fire hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



Photo # 3417 Dead weeds/debris near wellheads & chemical tank that is causing a fire hazard



Photo # 3418 Dead weeds/debris near wellheads & chemical tank that is causing a fire hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



Photo # 3419 Dead weeds/debris near wellheads & chemical tank that is causing a fire hazard



Photo # 3420 Wildlife egress damaged/needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY B Pad

Location #: 335549



Photo # 3421 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3422 Tank label contains inaccurate info/does not comply with CECMC rules