

Operator: HPR

Location Name: Critter Creek 5-10H

Loc ID: 415892

Inspection: 693700067



CA: COGCC follow-up to spill closure for spill 457128 and inspection of unresolved spill 453495 Fifth Creek spill on 12/19/2017: 1 bbl of produced water and 2 bbls of Crude Oil was released outside of containment from the heater treater on the well pad of the Critter Creek 5-10H. The cause of the spill was determined to be due to the gasket on the flange halfway up the heater treater failed. Once the leak was discovered a crew was dispatched to location and 1 bbl of produced water and 2 bbls of Crude Oil were recovered. Operators submit Form 19 Supplemental Report for spill ID 453495 and include root cause/corrective action for release and documentation of remediation efforts (soil removed/disposed and confirm soil sample results).

CA Resolution: Operator has completed actions to repair the gasket and clean-up was previously performed to address the spill. Form 19 Doc # 401494187 was submitted to address the spill.