

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403873103

Date Received:
07/31/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

8 of 8 CAs from the FIR responded to on this Form

8 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10814

Name of Operator: MDS ENERGY DEVELOPMENT LLC

Address: 409 BUTLER RD SUITE A

City: KITTANNING State: PA Zip: 16201

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

SAADEH, RICHARD

jim.jacobsen@iptwell.com

richard.saadeh@mdsed.com

kelsi.welch@iptwell.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708201402

Inspection Date: 07/01/2024

FIR Submit Date: 07/10/2024

FIR Status: _____

Inspected Operator Information:

Company Name: MDS ENERGY DEVELOPMENT LLC

Company Number: 10814

Address: 409 BUTLER RD SUITE A

City: KITTANNING State: PA Zip: 16201

LOCATION - Location ID: 471039

Location Name: Castor 7-59

Number: 10

County: _____

Qtrqtr: SWSE Sec: 10 Twp: 7N Range: 59W Meridian: 6

Latitude: 40.583600 Longitude: -103.963208

FACILITY - API Number: 05-123-

-00

Facility ID: 471039

Facility Name: Castor 7-59

Number: 10

Qtrqtr: SWSE Sec: 10 Twp: 7N Range: 59W Meridian: 6

Latitude: 40.583600 Longitude: -103.963208

CORRECTIVE ACTIONS:

1 CA# 196675

Corrective Action: Properly dispose of oily waste in accordance with Rule 905.e.

Date: 07/25/2024

Response: CA COMPLETED

Date of Completion: 07/24/2024

Operator
Comment:

Oily waste has been cleaned up and properly disposed of in accordance with Rule 905.e.

ECMC Decision: _____

ECMC
Representative:

2 CA# 196676

Corrective Action: Install sign to comply with Rule 605.h.

Date: 08/10/2024

Response: CA COMPLETED

Date of Completion: 07/24/2024

Operator
Comment:

Sign installed on tank

ECMC Decision: _____

ECMC
Representative:

3 CA# 196677

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 07/25/2024

Response: CA COMPLETED

Date of Completion: 07/19/2024

Operator
Comment:

All valves, pipes, fittings and Production Facilities have been securely fastened.

ECMC Decision: _____

ECMC
Representative:

4 CA# 196678

Corrective Action: Install or repair wildlife protection equipment per Rule 902.b.

Date: 07/20/2024

Response: CA COMPLETED

Date of Completion: 07/15/2024

Operator
Comment:

Wildlife protection equipment has been installed or repaired for compliance with Rule 902.b.

ECMC Decision: _____

ECMC
Representative:

5 CA# 196679

Corrective Action: Install or repair wildlife protection equipment per Rule 902.b.

Date: 07/20/2024

Response: CA COMPLETED

Date of Completion: 07/19/2024

Operator
Comment:

Wildlife protection equipment has been installed or repaired for compliance with Rule 902.b.

ECMC Decision: _____

ECMC
Representative:

6 CA# 196680

Corrective Action: Comply with Rule 606 and manage weedy vegetation. Date: 07/18/2024

Response: CA COMPLETED Date of Completion: 07/20/2027

Operator Comment: Weed have been maintained for compliance with Rule 606.

ECMC Decision: _____

ECMC Representative: _____

7 CA# 196681

Corrective Action: Comply with Rule 606 and remove all trash and debris. Date: 07/18/2024

Response: CA COMPLETED Date of Completion: 07/18/2024

Operator Comment: Trash & debris have been removed.

ECMC Decision: _____

ECMC Representative: _____

8 CA# 196682

Corrective Action: Comply with Rule 1002.b. Operator shall import approximately 2,952 CY of topsoil to supplement the deficit for the minimum required 6" of topsoil. Corrective action date is being back-dated to when the location should have been in compliance. Date: 10/25/2022

Response: CA COMPLETED Date of Completion: 07/29/2024

Operator Comment: Interim reclamation activities, including topsoil importation, has begun. Please see full plan attached to sundry doc #403684816. Onsite inspection for topsoil importation activities with ECMC reclamation staff is scheduled 8/2/2024.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kelsi Welch

Signed: _____

Title: Permitting & Compliance

Date: 7/31/2024 4:59:23 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

--	--

Total Attach: 0 Files