

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2024

Submitted Date:

08/02/2024

Document Number:

707801052

FIELD INSPECTION FORM

Loc ID 334457 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10639

Name of Operator: CPX PICEANCE HOLDINGS LLC

Address: 34 S WYNDEN DR STE 240

City: HOUSTON State: TX Zip: 77056

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Kurtenbach, Nick		nick@cpxpiceance.com	

General Comment:**ECMC Inspection Report Summary**

On Thursday 8/1/2024, I, Inspector Scott Ramsey and Wayne Smelser, attempted to conduct routine inspection at CPX TPR 25A, at Location # 334457 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

We were unable to access location due to a locked gate that the supplied combo was not the correct one. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area.

I attempted to contact Nick Kurtenbach at 8:45 and left a message to inform him of us going to location. Upon arrival to locked gate and combo didn't work, I proceeded down to CPX central tank battery and called the two emergency numbers and had to leave a voicemail on both. We waited for an hour and no response from anyone. The next morning 8/2/24 at approximately 9 AM I received a voicemail from Nick stating he was traveling the day before but didn't know the new combo for the gate and was going to try to find out for us.

During this inspection the following compliance issues were observed:

1. No access to location (locked gate)
2. No immediate emergency contact response.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

Emergency Contact Number:

Comment: 1. No access to location (locked gate)
2. No immediate emergency contact response. (713-554-9031) (720-233-8275) (970-987-2220) See inspector comment

Corrective Action: Provide key, combinations, or alternate method of access to comply with rule 204.

Date: 08/03/2024

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date: