

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403842137

Date Received:

07/01/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 696306463

Inspection Date: 06/25/2024

FIR Submit Date: 06/25/2024

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 429977

Location Name: Antelope Number: F-15 PAD County: _____

Qtrqtr: NWN Sec: 15 Twp: 5N Range: 62W Meridian: 6
W

Latitude: 40.406060 Longitude: -104.314660

FACILITY - API Number: 05-123- -00 Facility ID: 429977

Facility Name: Antelope Number: F-15 PAD

Qtrqtr: NWN Sec: 15 Twp: 5N Range: 62W Meridian: 6
W

Latitude: 40.406060 Longitude: -104.314660

CORRECTIVE ACTIONS:

1 ☒ CA# 196115

Corrective Action: Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.

Date: 06/28/2024

Response: CA COMPLETED

Date of Completion: 07/01/2024

Operator has reported that identified risers have been appropriately marked to comply with Rule 1105.b.

Operator Comment:			
ECMC Decision:	Approved		
ECMC Representative:	Approved		

2

☒ CA# 196116

Corrective Action: Install sign to comply with Rule 605.h.

Date: 01/15/2023

Response: CA COMPLETED

Date of Completion: 07/01/2024

Operator Comment: Operator has reported that appropriate labels have now been installed to comply with Rule 605.h.

ECMC Decision: Approved

ECMC Representative: Approved

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr Regulatory Analyst

Date: 7/1/2024 3:50:30 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403842137	FIR RESOLUTION SUBMITTED
403842224	Inspection Report Resolution

Total Attach: 2 Files