

Click here to reset form



State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109



FOR OGCC USE ONLY

BRADENHEAD TEST REPORT

Step 1. Record all tubing and casing pressures as found.
Step 2. Sample now, if intermediate or surface casing pressure >25 psi. In sensitive areas, 1 psi.
Step 3. Conduct Bradenhead test.
Step 4. Conduct Intermediate casing test.
Step 5. Send report to BLM within 30 days and to OGCC within 10 days. Include wellbore diagram if not previously submitted or if wellbore configuration has changed since prior program. Attach gas and liquid analyses if sampled.

1. OGCC Operator Number: _____		3. BLM Lease No: _____		11. Date of Test: <u>7-28-24</u>	
2. Name of Operator: _____		5. Multiple completion? <input type="checkbox"/> Yes <input type="checkbox"/> No		12. Well Status: <input type="checkbox"/> Flowing <input type="checkbox"/> Shut In	
4. API Number: _____		6. Well Name: <u>Bigfoot</u>		<input checked="" type="checkbox"/> Gas Lift <input type="checkbox"/> Pumping <input type="checkbox"/> Injection	
7. Location (QtrQtr, Sec, Twp, Rng, Meridian): _____		8. County: _____		<input type="checkbox"/> Clock/Intermittent	
9. Field Name: _____		10. Minerals: <input type="checkbox"/> Fee <input type="checkbox"/> State <input type="checkbox"/> Federal <input type="checkbox"/> Indian		<input type="checkbox"/> Plunger Lift	
13. Number of Casing Strings: _____		14. STEP 1: EXISTING PRESSURES		15. _____	
16. _____		17. _____		STEP 2: See instructions above.	

STEP 3: BRADENHEAD TEST						
Buried valve? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Confirmed open? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		Elapsed Time (Min:Sec)	Fm: _____	Fm: _____	Production Casing PSIG	Intermediate Casing PSIG
With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals. Define characteristics of flow in "Bradenhead Flow" column using letter designations below: O = No Flow; C = Continuous; D = Down to 0; V = Vapor H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas			Tubing:	Tubing:		
BRADENHEAD SAMPLE TAKEN? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid		00:		257	692	No flow
Character of Bradenhead fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black <input type="checkbox"/> Other: (describe) _____		05:		268	691	No flow
Sample cylinder number: _____		10:		260	686	No flow
		15:		259	686	No flow
		20:		270	691	No flow
		25:		274	686	No flow
		30:		269	686	No flow
		Note instantaneous Bradenhead PSIG at end of test: > 0				

BH Fluid
No fluid
No fluid
No fluid
No fluid
No fluid
No fluid
No fluid
No fluid
No fluid

STEP 4: INTERMEDIATE CASING TEST						
Buried valve? <input type="checkbox"/> Yes <input type="checkbox"/> No Confirmed open? <input type="checkbox"/> Yes <input type="checkbox"/> No		Elapsed Time (Min:Sec)	Fm: _____	Fm: _____	Production Casing PSIG	Intermediate Casing PSIG
With gauges monitoring production casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals. Characterize flow in "Intermediate Flow" column using letter designations below: O = No Flow; C = Continuous; D = Down to 0; V = Vapor H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas			Tubing:	Tubing:		
INTERMEDIATE SAMPLE TAKEN? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid		00:				
Character of Intermediate fluid: <input type="checkbox"/> Clear <input type="checkbox"/> Fresh <input type="checkbox"/> Sulfur <input type="checkbox"/> Salty <input type="checkbox"/> Black <input type="checkbox"/> Other: (describe) _____		05:				
Sample cylinder number: _____		10:				
		15:				
		20:				
		25:				
		30:				
		Note instantaneous Intermediate Casing PSIG at end of test: >				

18. Comments: Annual Bradenhead Test: No Bradenhead psi observed.

19. STEP 5: See instructions above.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed by: Rudy Barroza Title: Production Supervisor Phone: 915-491-0311

Signed: _____ Title: _____ Date: _____

WITNESSED BY: _____ Title: _____ Agency: _____