

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 21-8 Pad
Location ID: 159692



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**

Section/Township/Range: 8 7S93W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 21-8 Pad
Location ID: 159692



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 21-8 Pad
Location ID: 159692



Photo # 4884 Failure to maintain chemical BMP - Chemical tank containment approximately 3/4 to 7/8 full of fluid/BMP insufficient to contain possible spill



Photo # 4885 Standing fluid on top of chemical tank containment/wildlife hazard

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 21-8 Pad
Location ID: 159692



Photo # 4886 Failure to maintain chemical BMP - Chemical tank containment approximately 3/4 to 7/8 full of fluid/BMP insufficient to contain possible spill



Photo # 4887 Standing fluid on top of chemical tank containment/wildlife hazard

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 21-8 Pad
Location ID: 159692



Photo # 4888 Failure to maintain chemical BMP - Chemical tank containment approximately 3/4 to 7/8 full of fluid/BMP insufficient to contain possible spill



Photo # 4889 Standing fluid on top of chemical tank containment/wildlife hazard