

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403853652

Date Received:  
07/15/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 992 S 4TH AVE SUITE 100-461  
City: BRIGHTON State: CO Zip: 80601

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Harms, Jason</u>		<u>Jason@strachanexploration.com</u>
<u>BEAR STACY L</u>		<u>stacy@strachanexploration.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601181  
Inspection Date: 06/26/2024 FIR Submit Date: 06/27/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: STRACHAN EXPLORATION INC Company Number: 83130  
Address: 992 S 4TH AVE SUITE 100-461  
City: BRIGHTON State: CO Zip: 80601

LOCATION - Location ID: 321229

Location Name: HOFFMAN, EARL-622S48W Number: 31N2NE County: BENT  
Qtrqr: N2NE Sec: 31 Twp: 22S Range: 48W Meridian: 6  
Latitude: 38.097825 Longitude: -102.838529

FACILITY - API Number: 05-011-00 Facility ID: 206379

Facility Name: HOFFMAN, EARL Number: 1  
Qtrqr: N2NE Sec: 31 Twp: 22S Range: 48W Meridian: 6  
Latitude: 38.097825 Longitude: -102.838529

CORRECTIVE ACTIONS:

1  CA# 196193

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o. Date: 06/27/2024

Response: CA COMPLETED Date of Completion: 07/24/2024

Operator Comment: Received an approved form 27 to remove the tank on Friday 7/12/24. Will remove the tank as soon as we can get the proper equipment to location to do so. BY 7/24 (But probable this week 7/19) Will sample per F27

ECMC Decision: Approved pending re-inspection

ECMC Representative: A follow up inspection will be performed to ensure tank is removed. FIRR including pictures should be submitted once tank has been removed.

2  CA# 196194

Corrective Action: Install sign to comply with Rule 605.d.

Date: 06/27/2024

Response: CA COMPLETED

Date of Completion: 07/19/2024

Operator Comment: Wellhead sign was ordered 6/28. Expect to get them this week. Will install immediately upon receipt

ECMC Decision: Approved pending re-inspection

ECMC Representative: As of 8/7/24, the sign had not been installed. FIRR including pictures should be submitted once new sign is installed.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Form 27 approval to remove tank was received 7/12/24. Will remove tank as soon as equipment is available. Will not rebuild berms. Awaiting sign arrival.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Shawn Reed

Signed: \_\_\_\_\_

Title: Petroleum Consultant

Date: 7/15/2024 6:21:00 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403853652	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files