

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403843610

Date Received:

07/02/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10797

Name of Operator: DESERT EAGLE OPERATING LLC

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Butler, Brad

972-345-9195

butleroil@yahoo.com

Bulf, Cathy

cathybulf@gmail.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601169

Inspection Date: 06/24/2024

FIR Submit Date: 06/25/2024

FIR Status: _____

Inspected Operator Information:

Company Name: DESERT EAGLE OPERATING LLC

Company Number: 10797

Address: 17101 PRESTON RD SUITE 105

City: DALLAS State: TX Zip: 75248

LOCATION - Location ID: 484358

Location Name: Red Rocks Number: 1-16 County: LAS ANIMAS

Qtrqr: NENE Sec: 1 Twp: 30S Range: 55W Meridian: 6

Latitude: 37.464488 Longitude: -103.518825

FACILITY - API Number: 05-071- -00 Facility ID: 484677

Facility Name: Red Rocks Number: 1-16

Qtrqr: NENE Sec: 1 Twp: 30S Range: 55W Meridian: 6

Latitude: 37.464488 Longitude: -103.518825

CORRECTIVE ACTIONS:

1 ☒ CA# 196132

Corrective Action: Operator shall abide by the reclamation rules to minimize surface disturbances per the 1002e.

Date: 06/26/2024

Response: CA COMPLETED

Date of Completion: 06/26/2024

Operator Comment: In order to reasonably minimize land disturbances and facilitate future reclamation, Desert Eagle Operating personnel, contractors, and other parties associated with the location have been instructed on Rule 1002.3. and to the extent possible not travel outside of the original access road boundary. The flowline right of way has been traversed for seeding and erosion mitigation, Desert Eagle Operating personnel, contractors, and other parties associated with the location have been instructed on Rule 1002.3. and to the extent possible not travel outside of

the flowline right of way.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Desert Eagle Operating (DEO) endeavors to operate in a manner that protects public health, safety, welfare, the environment and wildlife resources by complying with all the rules and regulations of the ECMC. The flowline right of way has traversed for seeding and erosion mitigation, Desert Eagle Operating personnel, contractors, and other parties associated with the location have been instructed on Rule 1002.3. and to the extent possible not travel outside of the roadway. Areas of the location were prepared and seeded; however, sparse germination has been attributed to several factors: lack of rain, lack of topsoil/soil amendments, and remaining areas of heavily compacted soils. DEO is preparing to address these issues with additional soil ripping, applying additional topsoil, and reseeding. The persistent draught is impeding progress. DEO continues to evaluate the identified drill cuttings waste and clean up at the north side of the location and is proceeding with drill cuttings clean up under Form 27

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cathy Bulf

Signed: _____

Title: Manager

Date: 7/2/2024 3:30:39 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number Description

403843610	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files