

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403860339

Date Received:
07/21/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10797
Name of Operator: DESERT EAGLE OPERATING LLC
Address: 17101 PRESTON RD SUITE 105
City: DALLAS State: TX Zip: 75248

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Butler, Brad</u>	<u>972-345-9195</u>	<u>butleroil@yahoo.com</u>
<u>Brandon Parks</u>	<u>469-790-6445</u>	<u>bparks33@gmail.com</u>
<u>Bulf, Cathy</u>		<u>cathybulf@gmail.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601166
Inspection Date: 06/24/2024 FIR Submit Date: 06/25/2024 FIR Status: _____

Inspected Operator Information:

Company Name: DESERT EAGLE OPERATING LLC Company Number: 10797
Address: 17101 PRESTON RD SUITE 105
City: DALLAS State: TX Zip: 75248

LOCATION - Location ID: 484357

Location Name: Red Rocks Number: 1-14 County: LAS ANIMAS
Qtrqr: NENW Sec: 1 Twp: 30S Range: 55W Meridian: 6
Latitude: 37.465273 Longitude: -103.526247

FACILITY - API Number: 05-071-00 Facility ID: 484674

Facility Name: Red Rocks Number: 1-14
Qtrqr: NENW Sec: 1 Twp: 30S Range: 55W Meridian: 6
Latitude: 37.465273 Longitude: -103.526247

CORRECTIVE ACTIONS:

1 CA# 196130

Corrective Action: Operator shall abide by the reclamation rules to minimize surface disturbances per the 1002e rule. Date: 06/26/2024

Response: CA COMPLETED Date of Completion: 07/03/2024

Operator Comment: In order to reasonably minimize land disturbances and facilitate future reclamation, Desert Eagle Operating personnel, contractors, and other parties associated with the location have been instructed on Rule 1002.3. and to the extent possible not travel outside of the original access road boundary. The flowline right of

way has has traversed for ripping, seeding, watering, and erosion mitigation.

ECMC Decision: Approved pending re-inspection

ECMC Representative:

2 CA# 196131

Corrective Action: Comply with 1003 Rules. Repair subsidence and reseed as needed.

Date: _____

Response: CA COMPLETED

Date of Completion: 07/03/2024

Operator Comment:

Reclamation is being monitored, topsoil and additional seeding will be applied as needed.

ECMC Decision: Approved pending re-inspection

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Desert Eagle Operating (DEO) endeavors to operate in a manner that protects public health, safety, welfare, the environment and wildlife resources by complying with all the rules and regulations of the ECMC. The flowline right of way has traversed for ripping, seeding, water application, and erosion mitigation, Desert Eagle Operating personnel, contractors, and other parties associated with the location have been instructed on Rule 1002.3. and to the extent possible not travel outside of the roadway. Areas of the location were prepared and seeded; however, sparse germination has been attributed to several factors: lack of rain, lack of topsoil/soil amendments, and remaining areas of heavily compacted soils. DEO is preparing to address these issues with additional soil ripping, applying additional topsoil, and reseeding. The persistent draught has been impeding progress.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cathy Bulf

Signed: _____

Title: Manager

Date: 7/21/2024 8:11:51 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403860339	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files