

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403887244

Date Received:

08/13/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>	<u>505-324-5188</u>	<u>pshorty@hilcorp.com</u>
<u>Jones, Tammy</u>		<u>FarmingtonRegulatoryTechs@hilcorp.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000824

Inspection Date: 06/12/2024

FIR Submit Date: 06/14/2024

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 306932

Location Name: UTE 34-10-M34N10W Number: 30SESE County: _____
Qtrqtr: SESE Sec: 30 Twp: 34N Range: 10W Meridian: M
Latitude: 37.157550 Longitude: -107.969460

FACILITY - API Number: 05-067- -00 Facility ID: 306932

Facility Name: UTE 34-10-M34N10W Number: 30SESE
Qtrqtr: SESE Sec: 30 Twp: 34N Range: 10W Meridian: M
Latitude: 37.157550 Longitude: -107.969460

CORRECTIVE ACTIONS:

1 ☒ CA# 195920

Corrective Action: Comply with rule 1002 Install or repair required BMPs.

Date: _____

Response: CA COMPLETED

Date of Completion: 08/12/2024

Operator Comment: Gully erosion has been mitigated and repaired. See attached photos.

ECMC Decision: Approved pending re-inspection

ECMC Representative:	Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.
----------------------	--

OPERATOR COMMENT AND SUBMITTAL

Comment: Gully erosion has been mitigated and repaired. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tammy Jones

Signed: _____

Title: Ops/Regulatory Tech

Date: 8/13/2024 9:43:28 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403887244	FIR RESOLUTION SUBMITTED
403887257	Resolved Photos

Total Attach: 2 Files