

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GOLDING 4 Pad
Location #: 335688



Location Overview: Location is within High Priority/Density Habitat areas. Location is approximately 12 yards from a Creek/Drainage that contributes to the Colorado River.

Section/Township/Range: 14 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GOLDING 4 Pad
Location #: 335688



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GOLDING 4 Pad
Location #: 335688



Photo # 6373 Chemical tanks in shed lack BMP's



Photo # 6374 Chemical tanks in shed lack BMP's



Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GOLDING 4 Pad
Location #: 335688



Photo # 6375 Hay bales/BMP's near creek/drainage have a large amount of sediment buildup & may need maintenance in the near future.



Photo # 6376 Hay bales/BMP's near creek/drainage have a large amount of sediment buildup & may need maintenance in the near future.