

**From:** Shad Brown <shbrown@hilcorp.com>  
**Sent:** Wednesday, September 4, 2024 10:18 AM  
**To:** Tammy Jones <tajones@hilcorp.com>; Bob Percell <bpercell@hilcorp.com>; Chad Perkins <cperkins@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>  
**Subject:** Re: HUBER SPC FEDERAL 2 14 - INC - 714001133

Weeds have been sprayed.

Shad Brown  
 Area 1  
 505-609-3449  
 505-634-8207

<b>Today's Date:</b>	8/29/2024					
<b>Well Name:</b>	HUBER SPC FEDERAL 2 14	<b>Location:</b>	Sec: 14	Twon: 035N	Rng: 008W	UL: O
<b>API Number:</b>	05.067.07645	<b>Footage:</b>	990 FSL, 1500 FWL			
<b>Operator:</b>	Hilcorp Energy Company	<b>Area/Run/MSO:</b>	01	0100	Bob Percell	
<b>Meter #:</b>		<b>Pipeline:</b>				
<b>INC Number:</b>	714001133	<b>Agency:</b>	COGCC	<b>Inspector:</b>	Corey McDonough	
<b>Type of INC:</b>	Written	<b>Photos Required:</b>	<b>Yes</b>	<b>Due Date:</b>	<b>9/4/2024</b>	
<b>Issue of Concern:</b>	<p>Comment: Infestation of Noxious weeds including but not limited to Mullein and Musk thistle observed on the location.</p> <p><b>Comply with rule 1004.e, treat/remove weeds.</b></p> <p><b>Overall Final Reclamation – FAIL - Location is Federal Surface- Location remains subject to 1004 requirements, however final passing by the ECMC is subject to Federal Approval. Operator shall provide signed documentation from the BLM for any work to be done, or not done, in a manner that does not comport with ECMC rules; documentation shall be attached to a Form 4 Sundry Notice for ECMC Staff review.</b></p>					







