

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2024

Submitted Date:

09/06/2024

Document Number:

715500619

**FIELD INSPECTION FORM**Loc ID 420072 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

18 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	(970) 285-9377	COGCCInspectionReports@terraep.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420071	WELL	SI	02/01/2024	OW	103-11815	RG FEDERAL 4D-34D	SI

**General Comment:****ECMC Inspection Report Summary**

On Thursday, 09/05/2024, Inspector Kirby Burchett, conducted a follow up field inspection at TEP Rocky Mountain LLC on the RG Federal 4D-34D well, Location #420072, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District and Black Bear area with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #702501934 on 10/29/23. All Corrective Actions have been resolved.

While there during normal operations the following compliance issues were observed:

1. Unused equipment.
2. Faded chemical label.
3. Relief riser missing cap.
4. Unplugged ball valves on gas line with handles installed.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Faded and illegible label needs replaced		
Corrective Action:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.	Date:	09/16/2024

**Emergency Contact Number:**

Comment: 970-285-9377

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Gas supply line inside tank battery with unplugged valves and handles subject to accidental gas release		
Corrective Action:	Install secondary plugs to prevent accidental gas discharge	Date:	09/16/2024
Type	UNUSED EQUIPMENT		
Comment:	Methanol tank and part of pump not in use		
Corrective Action:	All equipment not hooked up or out of service will be removed from location.	Date:	09/21/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Livestock panels		

Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Livestock panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank on containment		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Methanol tank in containment. Out of service.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Relief riser missing protective cap		
Corrective Action:	Vents on pressure safety devices will terminate in a manner so as not to endanger the public or adjoining facilities. They will be designed to be clear and free of debris and water at all times.	Date:	09/16/2024
Type: Gas Meter Run	# 1		
Comment:	Inside separator		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	400 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment:	Lined				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					
				Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Lined			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	420071	Type:	WELL	API Number:	103-11815	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>Shut In - February 2024 June 2024 Production Report</div>									
Corrective Action: _____ Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
		Ditches				
				Material Handling And Spill Prevention		
Ditches						
Drains						

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715500620	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6695653">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6695653</a>