

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/21/2024

Submitted Date:

09/06/2024

Document Number:

696206184

## FIELD INSPECTION FORM

 Loc ID 313134 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7 Number of Comments  
 2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**
 ECMC Operator Number: 10396  
 Name of Operator: SWN PRODUCTION COMPANY LLC  
 Address: P.O. BOX 12359  
 City: SPRING State: TX Zip: 77391-
**Contact Information:**

Contact Name	Phone	Email	Comment
Gee, Elizabeth	(832) 796-2873	liz_gee@swn.com	All Inspections
, SWN		swnsandwash@swn.com	All Inspections
Maneotis, Karen		Karen_Maneotis@swn.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259578	WELL	PA	06/10/2022	CBM	081-07050	WALKER 3-1	RI
313134	LOCATION	CL			-	WALKER 7-93-3 PAD1	RI

**General Comment:**

On 8/21/2024, Reclamation Specialist Trujillo conducted a final reclamation inspection at SWN Production Company LLC's Walker 3-1 location in Moffat County, Colorado.

This inspection is in response to Form 4 #403816926 stating "Final Reclamation Complete".

It was observed in this inspection that reclamation has not been completed pursuant to 1004 requirements.

The following compliance issues were observed during this inspection:

- Final Reclamation of Location and Access road
- Weeds
- Utility Equipment remaining
- Protection of Soils

Refer to the Reclamation section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

**Inspected Facilities**

Facility ID: 259578 Type: WELL API Number: 081-07050 Status: PA Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 313134 Type: LOCATION API Number: - Status: CL Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_ Fail \_\_\_\_\_

Comment Soil stockpile/berm was not contoured/replaced to the locations original relative grade during reclamation (see "Final Reclamation" below). BMPs to protect the stockpiled soils from erosion, degradation, weed establishment, as well as to minimize sediment transport are missing or insufficient.

Corrective Action Comply with Rules 1002.c and 1002.f. Temporary BMPs will be required until reclamation is performed. Date **09/13/2024**

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed \_\_\_\_\_

Gravel removed **Fail**

Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured **Fail**

Compaction alleviation **Fail** Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage \_\_\_\_\_

Weeds present **Fail** Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date **10/15/2024**

Conduct reclamation in accordance with 1004 rules at the Location/Road including, but not limited to removal of utility equipment and gravel material, compaction alleviation, recontour/regrading and establish vegetation with total perennial, non-invasive uniform plant cover of at least 80% of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district.

Comply with Rule 1002.f and ensure erosion controls are implemented to stabilize the seeded soil.

Comply with Rules 1004.e and 606.c: Oil and Gas Locations will be kept free of all Undesirable Plant Species.

Ongoing stormwater and weed management required until Final Reclamation has passed.

Overall Final Reclamation **Fail** Well Release on Active Location  Multi-Well Location

**ECMC Comments**

Comment	User	Date
<p>Pursuant to Rule 1004.a, all debris and surface equipment shall be removed within three (3) months of plugging a well. All access roads to plugged and abandoned wells and associated production facilities shall be closed, graded and recontoured. Well locations, access roads and associated facilities shall be reclaimed. As applicable, compaction alleviation, restoration, and revegetation of well sites, associated production facilities, and access roads shall be performed to the same standards as established for interim reclamation under Rule 1003. All other equipment, supplies, weeds, rubbish, and other waste material shall be removed. All such reclamation work shall be completed within twelve (12) months on non-crop land after plugging a well or final closure of associated production facilities.</p> <p>It was observed in this inspection that the Location, and the access road to the Location have not been reclaimed in accordance with ECMC 1004 Rules. Contour work is inadequate as fill slopes and stockpiled soils/berm remain on the west end of the Location. Additionally, utility equipment on, and leading to the Location has not been removed. Noxious weeds (Scotch thistle, Knapweed) observed established on the Location. There are areas on the south end of the Location that remain predominantly bare and have not achieved a uniform desirable perennial vegetative establishment. It was also observed that species planted do not reflect species within the adjacent undisturbed reference areas, or vegetation that existed pre-disturbance; records show surface owner approved of the mix.</p>	trujilloam	09/06/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696206185	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6696360">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6696360</a>