

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403788334

Date Received:

08/12/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 697505252

Inspection Date: 04/04/2024

FIR Submit Date: 04/09/2024

FIR Status: _____

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION

Company Number: 10071

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 420523

Location Name: Critter Creek Number: 24-30H County: _____

Qtrqtr: SESE Sec: 30 Twp: 11N Range: 63W Meridian: 6

Latitude: 40.887078 Longitude: -104.468097

FACILITY - API Number: 05-123- -00 Facility ID: 420523

Facility Name: Critter Creek Number: 24-30H

Qtrqtr: SESE Sec: 30 Twp: 11N Range: 63W Meridian: 6

Latitude: 40.887078 Longitude: -104.468097

CORRECTIVE ACTIONS:

1 ☒ CA# 194127

Corrective Action: Comply with Rule 1004. Remove gravel, recontour, cross-rip access road to depth of eighteen (18) inches, reclaim the access road, and perform weed management throughout the location.

Date: 05/13/2024

Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Response: CA COMPLETED

Date of Completion: 05/10/2024

Operator Comment: Operator has reported that this location mowed and sprayed for undesirable vegetation. The old access was scraped to remove remaining road-base material. Topsoil was imported to fill low areas in the access area and cap the access area. Area was ripped, seeded and straw crimped to provide stabilization. Location complies with Rule 1004.

ECMC Decision: Approved

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr Regulatory Analyst

Date: 8/12/2024 7:53:18 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|------------------------------|
| 403788334 | FIR RESOLUTION SUBMITTED |
| 403885335 | Inspection Report Resolution |

Total Attach: 2 Files