

CORRECTIVE ACTION REPSONSE

DOCUMENT NUMBER: 713400255
FACILITY NAME: SKINNER RIDGE 35-AV
Location: CHEVRON USA INC SKR-65S98W/35NWNE
Location ID: 336045

CORRECTIVE ACTION COMMENT:

Multiple debris on location, refer to photos.

CORRECTIVE ACTION RESPONSE:

On the day of the receipt of this inspection report (28 August 2024) and corrective actions noted the Skinner Ridge Well Pad 35-AV was gone over by Chevron crews and all debris was removed from the pad and properly disposed of. Additional pictures of cleaned location are on the last 2 pages of this response.

On 27 August 2024 well heads 10 and 12 were hydro excavated in preparation for the well heads being cut of and properly plugged.

On 28 August 2024 well heads 10 and 12 were cut off as well as all out of service SCADA equipment and wires were removed as noted in the following pictures:





**OUT OF SERVICE WIRES
BEING CUT OFF BELOW
SURFACE GRADE**



CORRECTIVE ACTION COMMENT:

[Stockpiled soils with no BMP's, refer to photos.](#)

CORRECTIVE ACTION RESPONSE:

This is a stockpile of clean sand to be used in the backfilling of the excavation for the 35-AV well 10 and 12 cut off once soil sample lab results are received. See photos above and following:



Stockpiled soils with no BMP's - Photo #04747

Below are pictures from location where debris has been removed - page 4-5



