

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/18/2024

Submitted Date:

09/19/2024

Document Number:

715500694

FIELD INSPECTION FORM

Loc ID: 315743 Inspector Name: Burchett, Kirby On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10779
 Name of Operator: SCOUT ENERGY MANAGEMENT LLC
 Address: 13800 MONTFORT DRIVE SUITE 100
 City: DALLAS State: TX Zip: 75240

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Christian, Cody		Cody.Christian@scoutep.com	
Saint, John		jsaint@scoutep.com	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231483	WELL	AC	06/01/2023	OBW	103-09153	C. T. CARNEY 44Y34	AC

General Comment:

[ECMC Inspection Report Summary](#)

On Wednesday, 09/18/2024, Inspector Kirby Burchett, conducted a routine field inspection at Scout Energy Management LLC on the C. T. Carney 44Y34 well, Location #315743, in Rio Blanco County, Colorado.

This location is within or close proximity to a Parks & Wildlife (CPW) District with High Priority, NSO and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issue was observed:

1. Evidence of spill

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text" value="970-675-3700"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

Spills:

Type	Area	Volume			
Produced Water	WELLHEAD				
Comment:	Spilled fluid with soil contamination				
Corrective Action:	Remove and properly dispose of any stained and contaminated soil to an approved facility.			Date:	10/04/2024

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Type: Bradenhead	# 1			
Comment:				
Corrective Action:		Date:		
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:		Date:		
Type: Other	# 1			
Comment:	Wellhead tree			
Corrective Action:		Date:		

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:

Date:

Inspected Facilities

Facility ID: 231483 Type: WELL API Number: 103-09153 Status: AC Insp. Status: AC

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Active well for reservoir monitoring.
Last MIT - 4/29/21
June 2024 Production Report
Operators will report all existing oil and gas Wells that are not Plugged and Abandoned on the Form 7, Operator's Monthly Report of Operations within 45 days after the end of each month.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715500695	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6713704