

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2024

Submitted Date:

09/17/2024

Document Number:

713601444

**FIELD INSPECTION FORM**Loc ID 478057 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	
B WARD, GIENA		gward@ogrisop.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478058	TANK BATTERY	AC	09/17/2020		-	A.C. Tank Battery	RI

**General Comment:**

This is a follow up inspection of the A.C. Tank Battery.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Did not observe a tank battery sign.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	10/17/2024

**Emergency Contact Number:**

Comment:			
Corrective Action:		Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	There is inadequate netting covering the open top tank to prevent wildlife entry. There is a secondary containment which was full of oily fluids with no netting. Previous CA was not completed.		
Corrective Action:	Install or repair wildlife protection equipment. Comply with rule 902.b.	Date:	07/31/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
	Truck Loadout			
Comment:	There still appeared to be stained soils observed in front of the west tank battery. There was oily fluid spilled over the secondary containment.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 08/26/2024

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		There were erosion repairs since previous inspection. The check dams installed have filled in with sediment and need to be cleaned out. A larger sediment catch may be needed to prevent sediment movement onto the paved roadway. There are still signs of sediment and vehicle tracking onto the road that need to be cleaned up and controlled.				
Corrective Action:		Install or repair required BMPs per Rule 1002.f.(2)C				Date: 10/08/2024
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403924011	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6710300">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6710300</a>
713601445	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6710285">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6710285</a>