

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC DIAZ RWF 42-25 Pad
Location ID: 335504



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is approximately 241 yards from Beaver Creek.

Section/Township/Range: 25 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC DIAZ RWF 42-25 Pad
Location ID: 335504



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC DIAZ RWF 42-25 Pad
Location ID: 335504



Photo # 1702 Failure to maintain chemical BMP/chemical tank containment approximately 3/4th full of fluid/BMP insufficient to contain possible spill

Photo # 1703 Failure to maintain chemical BMP/chemical tank containment approximately 3/4th full of fluid/BMP insufficient to contain possible spill