

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2024

Submitted Date:

09/25/2024

Document Number:

717900032

## FIELD INSPECTION FORM

Loc ID 448663 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10459

Name of Operator: EXTRACTION OIL &amp; GAS INC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@Extracti onog.com	All Inspections
,		COGCCInspections@extracti onog.com	All Inspectons
Oil, Extraction	720-370-5540	COGCCInspections@extracti onog.com	

**General Comment:**

This is an environmental inspection for Location ID 448663 Farr Farms Location 1. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment: Statewide unnecessary equipment, weeds, waste, and trash requirements. Unused hose on site.

Corrective Action: Comply with Rule 606

Date: 10/09/2024

Overall Good: ☐**Spills:**

Type

Area

Volume

Comment: Soil staining observed underneath valve/piping connecting to a meter house.

Corrective Action: "For localized stained soils or oily waste - ""Properly dispose of oily waste in accordance with 905.e.""

For larger instances: ""Properly dispose of oily waste in accordance with Rule 905.e and contact area COGCC EPS""

Date: 10/09/2024

In Containment: No

Comment: No spills observed during inspection. However slight soil staining was observed.

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Berms around separator are inadequate to contain a potential spill. Need to be built up and recompacted.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.				Date: 10/25/2024

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Environmental

Spills/Releases:

Type of Spill:Estimated Spill Volume:

Comment:

No spills or releases observed aside from the de minimus soil staining.

Corrective Action:

Date:

Reportable:GPS: LatLong

Proximity to Surface Water:Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:Owner Name:GPS :LatLong

Field Parameters:

Sample Location:Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717900033	photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6721372">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6721372</a>