

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Hoeppli RWF 32-36 Pad
Location ID: 335530



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is approximately 338 yards from Beaver Creek. Location is within Rule 411a Surface Water External Buffer.

Section/Township/Range: 36 6S94W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Hoepli RWF 32-36 Pad
Location ID: 335530



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Hoepli RWF 32-36 Pad
Location ID: 335530



Photo # 2358 Failure to maintain chemical BMP/Chemical tank containment approximately 3/4th full of fluid/BMP not sufficient to contain possible spill



Photo # 2359 Improperly stored fuel container