

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403939301

Date Received:
09/30/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Caerus

COGCC.inspections@caerusoilandgas.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708904448

Inspection Date: 08/28/2024

FIR Submit Date: 08/30/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334283

Location Name: SHIDELER-67S92W Number: 31SENE County: _____

Qtrqtr: SENE Sec: 31 Twp: 7S Range: 92W Meridian: 6

Latitude: 39.405970 Longitude: -107.699480

FACILITY - API Number: 05-045- -00 Facility ID: 334283

Facility Name: SHIDELER-67S92W Number: 31SENE

Qtrqtr: SENE Sec: 31 Twp: 7S Range: 92W Meridian: 6

Latitude: 39.405970 Longitude: -107.699480

CORRECTIVE ACTIONS:

1 CA# 198209

Corrective Action: Comply with CECMC Stormwater rules

Date: 09/14/2024

Response: CA COMPLETED

Date of Completion: 09/05/2024

Operator
Comment: Subsidence repaired. See photo.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Justin Johnson

Signed:

Title: Compliance

Date: 9/30/2024 11:47:07 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403939310	Subsidence repair

Total Attach: 1 Files