

RESPONSE TO CORRECTIVE ACTION  
DOCUMENT NUMBER 713400336  
INSPECTION DATE: 23 SEPTEMBER 2024  
SKINNER RIDGE WELL PAD 698-11-1  
API NUMBER: 045-10713

CORRECTIVE ACTION FROM INSPECTION REPORT: [Tanks and Berms - Hole in secondary containment liner/liner needs maintenance with a CA date of 10/15/2024.](#)

Response to the above finding. On 30 September 2024 the hole that was found in the 11-1 tank liner was patched with appropriate tank liner repair material. See pictures below.

From the inspection report:



Hole in containment liner - Photo #06164

Before repair on 30 September 2024:



After repair on 30 September 2024:





RESPONSE TO CORRECTIVE ACTION  
DOCUMENT NUMBER 713400336  
INSPECTION DATE: 23 SEPTEMBER 2024  
SKINNER RIDGE WELL PAD 698-11-1  
API NUMBER: 045-10713

CORRECTIVE ACTION FROM INSPECTION REPORT: [Equipment - Separator door open to wildlife with a CA date of 10/4/2024](#)

Response to the above finding. On 30 September separator door was closed.



CORRECTIVE ACTION FROM INSPECTION REPORT: [Signs/Marker - No labeling on chemical tank, missing required information with a CA date of 10/27/2024](#)

Response to the above finding. On 30 September 2024 labeling was added to chemical tanks to comply with CECMC labeling rules.

