

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403913766

Date Received:  
09/09/2024

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10071  
Name of Operator: HIGHPOINT OPERATING CORPORATION  
Address: 555 17TH ST STE 3700  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Luke Kelly</u>	<u>970-939-6353</u>	<u>lkelly@civiresources.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 717700312  
Inspection Date: 09/03/2024 FIR Submit Date: 09/03/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION Company Number: 10071  
Address: 555 17TH ST STE 3700  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 451928

Location Name: Anschutz Equus Farms Number: 4-62-32 SESE County: \_\_\_\_\_  
Qtrqr: SESE Sec: 32 Twp: 4N Range: 62W Meridian: 6  
Latitude: 40.264911 Longitude: -104.339769

FACILITY - API Number: 05-123-00 Facility ID: 451928

Facility Name: Anschutz Equus Farms Number: 4-62-32 SESE  
Qtrqr: SESE Sec: 32 Twp: 4N Range: 62W Meridian: 6  
Latitude: 40.264911 Longitude: -104.339769

**CORRECTIVE ACTIONS:**

**1** CA# 198270

Corrective Action: Comply with the 1100 rules. Date: 12/31/2024

Response: CA COMPLETED Date of Completion: 09/09/2024

Operator Comment: Operator has addressed the issue and future use tags have been installed on all unused risers in order to comply with the 1100 series.

ECMC Decision: \_\_\_\_\_

ECMC Representative:

2 CA# 198271

Corrective Action: Comply with Rule 606

Date: 12/31/2024

Response: CA COMPLETED

Date of Completion: 09/09/2024

Operator Comment: Operator has addressed the unused equipment, it is there because of a separator swap that is in progress. The separator is currently in the shop being repaired; all of this equipment will be reinstalled on the separator once it's repaired. Confirmed with A.Burns this statement will suffice to close out this CA 9/9/2024.

ECMC Decision:

ECMC Representative:

3 CA# 198272

Corrective Action: Comply with the 1100 rules.

Date: 12/31/2024

Response: CA COMPLETED

Date of Completion: 09/09/2024

Operator Comment: Operator has addressed the issue and future use tags have been installed on all unused risers in order to comply with the 1100 series.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed:

Title: Sr Regulatory Analyst

Date: 9/9/2024 12:37:25 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403913766	FIR RESOLUTION SUBMITTED
403913776	Inspection Report Resolution

Total Attach: 2 Files