

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403918684

Date Received:
09/12/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 760 HORIZON DRIVE STE 401
City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Olson, Andrew</u>		<u>AndrewOlson@chevron.com</u>
<u>Kellerby, Shaun</u>		<u>shaun.kellerby@state.co.us</u>
<u>Aaron Katz</u>		<u>aaron.katz@state.co.us</u>
<u>Haverkamp, Curtis</u>		<u>curtis.haverkamp@state.co.us</u>
<u>Chevron Inspection Team</u>		<u>rbucogccinspectionreports@chevron.com</u>
<u>Bittner, Dawn</u>		<u>StephanieBittner@chevron.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 713400259
Inspection Date: 08/16/2024 FIR Submit Date: 08/26/2024 FIR Status:

Inspected Operator Information:

Company Name: CHEVRON USA INC Company Number: 16700
Address: 760 HORIZON DRIVE STE 401
City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 336045

Location Name: SKR-65S98W Number: 35NWNE County:
Qtrqr: NWNE Sec: 35 Twp: 5S Range: 98W Meridian: 6
Latitude: 39.574698 Longitude: -108.353573

FACILITY - API Number: 05-045-00 Facility ID: 336045

Facility Name: SKR-65S98W Number: 35NWNE
Qtrqr: NWNE Sec: 35 Twp: 5S Range: 98W Meridian: 6
Latitude: 39.574698 Longitude: -108.353573

CORRECTIVE ACTIONS:

1 CA# 197937

Corrective Action: Contact engineering.

Date: 09/02/2024

Response: CA COMPLETED

Date of Completion: 09/11/2024

Operator Comment: Well SKR-598-35-AV10 was plugged on 5/11 and at the same time we were moving from one system of scheduling (Generwell) to a new system of scheduling (Execute). During that migration some data was lost and our scheduling team did not receive the normal prompts to have the form submitted, but the work was already on the rig schedule. The rig went and executed the work and successfully plugged the well. In August it was realized that the well was missed and a form 42 was submitted retroactively. Due to this form being submitted, an inspector went out to the well and saw it was already plugged, prompting him to report a corrective action. Our engineering team (Gavin Snyder) has reached out to the states engineering team (Aaron Katz) and explained the situation, and the state expressed its understanding.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: The Corrective Action has been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dawn Bittner

Signed: _____

Title: Administrative Assistant

Date: 9/12/2024 11:07:33 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403918684	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files