

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403918737

Date Received:

09/19/2024

## FIR RESOLUTION FORM

**Overall Status:**

**CA Summary:**

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

**Additional Operator Contact:**

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 708201512

Inspection Date: 08/13/2024

FIR Submit Date: 08/16/2024

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: CRESTONE PEAK RESOURCES OPERATING LLC

Company Number: 10633

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

**LOCATION - Location ID: 331608**

Location Name: CHAPIN 61N65W Number: / 4 SESE County: \_\_\_\_\_

Qtrqtr: SESE Sec: 4 Twp: 1N Range: 65W Meridian: 6

Latitude: 40.075060 Longitude: -104.661820

**FACILITY - API Number: 05-123- -00 Facility ID: 331608**

Facility Name: CHAPIN 61N65W Number: / 4 SESE

Qtrqtr: SESE Sec: 4 Twp: 1N Range: 65W Meridian: 6

Latitude: 40.075060 Longitude: -104.661820

**CORRECTIVE ACTIONS:**

1 CA# 197777

Corrective Action: Comply with Rule 606 and remove any trash/debris and unused equipment from location.

Date: 08/23/2024

Response: CA COMPLETED

Date of Completion: 09/04/2024

Operator  
Comment:

Operation has addressed identified trash/debris and location now complies with the 600 series.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 197778

Corrective Action: Perform reclamation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 09/04/2024

Operator Comment: Operator has reported that the location has also been mowed, line trimmed. It has also been noted that the road base removal and seeding has been scheduled.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

3 CA# 197779

Corrective Action: Comply with Rule 1002.f.

Date: 08/30/2024

Response: CA COMPLETED

Date of Completion: 09/04/2024

Operator Comment: Operator has reported that identified areas of erosion have been appropriately stabilized and riprap refreshed to comply with Rule 1002.f.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: \_\_\_\_\_

Title: Sr Regulatory Analyst

Date: 9/19/2024 7:46:16 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403918737	FIR RESOLUTION SUBMITTED
403927190	Inspection Report Resolution

Total Attach: 2 Files