

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 13-7 Pad
Location ID: 323944



**Location Overview: Location is within Black Bear Habitat area
& in close proximity High Priority/NSO Habitat areas. Location
is within Rule 411a Surface Water External Buffer
Section/Township/Range: 7 7S93W**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 13-7 Pad
Location ID: 323944



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC YOUBERG RU 13-7 Pad
Location ID: 323944



Photo # 3378 Sediment trap needs maintenance/large amount of sediment in catch basin/sediment laden stormwater entering drain & being carried off location



Photo # 3379 Sediment trap needs maintenance/large amount of sediment in catch basin/sediment laden stormwater entering drain & being carried off location

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC YOUBERG RU 13-7 Pad
Location ID: 323944



Photo # 3380 Erosion & sediment transport on slope near drain line



Photo # 3381 Erosion & sediment transport on slope near drain line

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC YOUBERG RU 13-7 Pad
Location ID: 323944



Oct 2, 2024 at 1:01:22 PM



Oct 2, 2024 at 1:01:43 PM

Photo # 3382 Drain line showing signs of damage

Photo # 3383 Drain line showing signs of damage

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC YOUBERG RU 13-7 Pad
Location ID: 323944



Photo # 3384 Erosion & sediment transport at drain line outlet/BMP's need maintenance



Photo # 3385 Ditch along lease road needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC YOUBERG RU 13-7 Pad
Location ID: 323944



Photo # 3386 Ditch along lease road needs maintenance



Photo # 3387 Ditch along lease road needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC YUBERG RU 13-7 Pad
Location ID: 323944



Photo # 3388 Ditch along lease road needs maintenance