

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/01/2024

Submitted Date:

10/03/2024

Document Number:

713901056**FIELD INSPECTION FORM**Loc ID 458676 Inspector Name: Hansen, Logan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10518Name of Operator: CONFLUENCE DJ LLCAddress: 1401 WYNKOOP STREET STE 120City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		brothe@confluencelp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458676	LOCATION	AC			-	Silverton 4 North	RI

General Comment:[This is an Interim Reclamation and Stormwater Inspection.](#)

LocationOverall Good: ☐

Signs/Marker:			
Type			
Comment:	Signs not posted on the tank batteries.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	11/03/2024

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type			
Comment:	Broken hose apparently still in use was observed during the inspection.		
Corrective Action:	Replace and maintain equipment per Rule 608.	Date:	10/10/2024
Type			
Comment:	Stained soil observed around the Silverton 5-4-2L wellhead and tank on the southwest side of the production pad.		
Corrective Action:	Clean up stained soils per Rule 912.a.	Date:	11/03/2024
Type			
Comment:	Weed debris in the form of tumbleweeds were observed within all interim areas as dead old growth and newly germinated growth. Tumbleweeds are a troublesome annual non-native weed that easily breaks off at the stem. Operator failed to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. The Operator shall comply with Rule 606 by removing and managing all weed debris and growth.		
Corrective Action:			Date:

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type:	#		
Comment:	During the inspection it was observed that there were free fluids in two secondary containment units on the southwest area of the production pad. This resulted in a wildlife mortality. See inspection photos for details.		
Corrective Action:	Comply with Rule 902.b to remove and properly dispose of fluids from within secondary containment.	Date:	10/10/2024

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	458676	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment _____

Topsoil stockpile has significant weed cover- Russian thistle and Kochia- with no perennial vegetation that would compete with the weedy vegetation and generally work to decrease weed growth.

Corrective Action _____

Best management practices to prevent weed establishment shall be implemented. Control, manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseeding is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted.

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Appears the Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations. See Good Housekeeping and 1002.c Protection of Soils sections for details pertaining to management of interim areas. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management. Operator shall submit a Form 4 Interim Reclamation Complete notice when the location meets Rule 1003 standards. ECMC may conduct inspections prior to receiving said notice to ensure compliance with Rule 1003.

Corrective Action

Date _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

At the time of this inspection, no erosion issues were observed at the location or along the access road.

Operator shall continue to monitor and manage this site for stormwater run on and runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403944784	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6731997
713901057	Inspection photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6731976