

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403881859

Date Received:
10/11/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 5 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10810

Name of Operator: MESSER LLC

Address: 200 SOMERSET CORP BLVD #7000

City: BRIDGEWATER State: NJ Zip: 08807

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Twitty, Melita</u>	<u>(908) 771-1894</u>	<u>Melita.twitty@messer-us.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Hartman, Laura</u>		<u>lhartman@blm.gov</u>
<u>Engineering, General</u>		<u>dnr_ecmc_engineering@state.co.us</u>
<u>DeMarco, Jaime</u>		<u>jdemarco@blm.gov</u>
<u>Hom, Brian</u>	<u>(908) 771-1625</u>	<u>Brian.hom@messer-us.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 712700785

Inspection Date: 10/25/2023 FIR Submit Date: 10/26/2023 FIR Status: _____

Inspected Operator Information:

Company Name: MESSER LLC Company Number: 10810

Address: 200 SOMERSET CORP BLVD #7000

City: BRIDGEWATER State: NJ Zip: 08807

LOCATION - Location ID: 313551

Location Name: AIRCO DUDLEY-N36N18W Number: 13NWSW County: MONTEZUMA

Qtrqtr: NWS Sec: 13 Twp: 36N Range: 18W Meridian: N
W

Latitude: 37.373650 Longitude: -108.788083

FACILITY - API Number: 05-083-00 Facility ID: 224457

Facility Name: AIRCO DUDLEY Number: 5

Qtrqtr: NWS Sec: 13 Twp: 36N Range: 18W Meridian: N
W

Latitude: 37.373650 Longitude: -108.788083

CORRECTIVE ACTIONS:

1 CA# 187066

Corrective Action:

Date: 11/10/2023

Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).

Response: CA COMPLETED

Date of Completion: 11/10/2023

Operator Comment: Meter calibration record now displayed. Photo attached as 'Dudley meter calibration'.

ECMC Decision:

ECMC Representative:

2 CA# 187067

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).

Date: 11/10/2023

Response: CA COMPLETED

Date of Completion: 11/10/2023

Operator Comment: Valve was buried in dirt. Dirt has now been removed to expose valve. Valve in need of maintenance for operation--team working towards correction. Will advise once valve is operational. Photo attached of exposed valve as 'Dudley Bradenhead Valve'.

ECMC Decision:

ECMC Representative:

5 CA# 187070

Corrective Action: Perform annual bradenhead test and submit Form 17 per Rule 419.c.

Date:

Response: CA COMPLETED

Date of Completion: 07/25/2024

Operator Comment: Test completed 7/25/2024. Form 17 Doc# 403648443 submitted accordingly.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: FIRR being submitted to reference the Form 17 403881859 Bradenhead test satisfying CA 187070

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessie Wilson Signed:

Title: Analyst Date: 10/11/2024 1:11:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (http://ecmcweblink.state.co.us/) - Search by Document Number.

Table with 2 columns: Document Number, Description

Total Attach: 0 Files