

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403955682

Date Received:
10/14/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

0 CA Completed
2 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10417
Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC
Address: 113 N SANTA FE AVE
City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Harkins, Liz	719-429-4513	lharkins@fremontpetroleum.com
Hart, Tim	303-999-5420	thart@axpenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601508
Inspection Date: 10/09/2024 FIR Submit Date: 10/10/2024 FIR Status:

Inspected Operator Information:

Company Name: INCREMENTAL OIL & GAS (FLORENCE) LLC Company Number: 10417
Address: 113 N SANTA FE AVE
City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 417859

Location Name: Woolly Bugger Number: 34-20 County: FREMONT
Qtrqr: SWSE Sec: 20 Twp: 19S Range: 69W Meridian: 6
Latitude: 38.376641 Longitude: -105.132744

FACILITY - API Number: 05-043-00 Facility ID: 417858

Facility Name: Woolly Bugger Number: 34-20
Qtrqr: SWSE Sec: 20 Twp: 19S Range: 69W Meridian: 6
Latitude: 38.376641 Longitude: -105.132744

CORRECTIVE ACTIONS:

1 CA# 199526

Corrective Action: Submit an eForm 44 Flowline Report per Rule 1101.a. Date: 10/10/2024

Response: FACTUAL REVIEW REQUEST

Basis for Review: Requested documentation was submitted prior to the inspection

Operator Comment: We received two Inspections #713600524 (12/21/23) and #713600644 (1/23/24) issued by ECMC Field Inspector Ryan Costa indicating the off-location flowline for the Woolly Bugger 34-20 well had not been registered via Form 44. Operator followed through to fill out the Form 44, Doc #403680571 and submitted it on 3/25/24 amidst discussions with Steve Wheeler on 3/22/24. It was approved on 3/26/24, We are unsure why Inspector Ryan

Costa continues to cite the flowline registration as incomplete.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 199527

Corrective Action: Comply with 1003 Interim reclamation Rules.

Date: _____

Response: FACTUAL REVIEW REQUEST

Basis for Review: Findings are inappropriately tied to multiple wells

Operator Comment:

The area addressed by Inspector Ryan Costa has been previously addressed on the Apache 33B-20 inspections (713600522, 713600850, 713601052 & 713601510) to complete reclamation. The land owner has waived reclamation requirements and has asked for the location to remain "as is" for a potential home site once all oil activity is complete. The Operator is currently working with Ardor Environmental and McGowne Law Firm to seek a VARIANCE to WAIVE RECLAMATION on this site.
The Operator has taken steps to remove weeds near the location throughout the entire year. Operator has also seeded and straw-crimped the addressed area but it has yet to establish vegetation (an on-going task on the desert soil, with most recent seeding on 10/08/24). SEE ATTACHED PHOTOS

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment:

Operator was cited for not having a Form 44 submitted on this well. Form 44, Doc #403680571 was approved 3/26/24. Operator was cited for not having established vegetation on the west side of tank battery. Operator reseeded/strawed the area but it has yet to establish vegetation.....continues to be an on-going task for the desert soil. The subject well is in the vicinity of the Apache 33B well that was P&A'd 11/2022. Operator is seeking a variance to waive reclamation and turn over the site "as is" to the landowner per his request.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Liz Harkins

Signed: _____

Title: Engineer

Date: 10/14/2024 1:01:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403955682	FIR RESOLUTION SUBMITTED
403955870	Form 44, Approved
403955936	Photos of SEEDING to establish vegetation
403955971	Photos of STRAW and CRIMPING

Total Attach: 4 Files