

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403957059

Date Received:  
10/15/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>CAERUS</u>		<u>ecmc.inspections@qb-energy.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302880  
Inspection Date: 10/08/2024 FIR Submit Date: 10/08/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335670

Location Name: N.PARACHUTE-65S95W Number: 30SESW County: \_\_\_\_\_  
Qtrqtr: SESW Sec: 30 Twp: 5S Range: 95W Meridian: 6  
Latitude: 39.580910 Longitude: -108.098910

FACILITY - API Number: 05-045-00 Facility ID: 335670

Facility Name: N.PARACHUTE-65S95W Number: 30SESW  
Qtrqtr: SESW Sec: 30 Twp: 5S Range: 95W Meridian: 6  
Latitude: 39.580910 Longitude: -108.098910

CORRECTIVE ACTIONS:

**1** CA# 199430

Corrective Action: Repair wildlife protective equipment. Date: 10/13/2024

Response: CA COMPLETED Date of Completion: 10/13/2024

Operator Comment: Repaired tank screen to prevent wildlife entrance.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 199431

Corrective Action: Secure equipment to comply with Rule 608.e.

Date: 10/13/2024

Response: CA COMPLETED

Date of Completion: 10/13/2024

Operator Comment: Installed bull plug on meter manifold to comply with rule 608.e.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**3** CA# 199432

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 10/23/2024

Response: CA COMPLETED

Date of Completion: 10/14/2024

Operator Comment: Stormwater crew addressed cut slope that sloughed off into tank containment to comply with 1002.f.(2) BMP.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joey Gracey

Signed: \_\_\_\_\_

Title: Compliance

Date: 10/15/2024 8:56:24 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403957065	Bullplug on meter manifold
403957068	Tank Screen
403957074	Stormwater tank containment

Total Attach: 3 Files