

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/14/2024

Submitted Date:

10/15/2024

Document Number:

708302906

**FIELD INSPECTION FORM**

Loc ID 334965 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275333	WELL	PR	07/31/2005	GW	045-13524	PA 22-6	PR
275334	WELL	PR	06/03/2005	GW	045-13523	PA 322-6	PR
275335	WELL	PR	07/06/2005	GW	045-13522	PA 422-6	PR
275336	WELL	PR	07/06/2005	GW	045-13521	PA 522-6	PR

**General Comment:**

[CECMC Inspection Report Summary](#)

On 10/14/2024 at approximately 10:50, Compliance Inspector Matthew Morris conducted a follow-up inspection at TEP ROCKY MOUNTAIN LLC, PA-67S95W/6SEW at Location ID #334965 in Garfield County, Colorado.

During the inspection, the following compliance issues were observed:

- 1) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date:

**Good Housekeeping:**

Type	OTHER		
Comment:	Wildlife egress installed in wellhead cellars.		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	

<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 275333 Type: WELL API Number: 045-13524 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 275334 Type: WELL API Number: 045-13523 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 275335 Type: WELL API Number: 045-13522 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 275336 Type: WELL API Number: 045-13521 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Compaction				
		Check Dams				
		Rip Rap				
Gravel						
		Other	Fail			Transport of sediment from lease road
Berms						
		Other	Fail			Insufficient erosion control
Ditches						
		Sediment Traps				
		Ditches				
Compaction						
Rip Rap						
Sediment Traps						
		Gravel				

Comment: [1\) Insufficient erosion control on lease road to location](#)  
[2\) Sediment transport from lease road into nearby vegetation](#)

Corrective Action: **1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.**

Date: 10/31/2024

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708302908	Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6747848">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6747848</a>