

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403962170

Date Received:

10/17/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Trujillo, Helen

notices@rlbayless.com

Thomas, John

505-326-2659

jthomas@rlbayless.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 707801096

Inspection Date: 08/28/2024

FIR Submit Date: 09/13/2024

FIR Status: _____

Inspected Operator Information:

Company Name: ROBERT L BAYLESS PRODUCER LLC

Company Number: 6720

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

LOCATION - Location ID: 316758

Location Name: DRY CREEK UNIT-65N88W Number: 22NENW County: _____

Qtrqtr: NENW Sec: 22 Twp: 5N Range: 88W Meridian: 6

Latitude: 40.379961 Longitude: -107.248449

FACILITY - API Number: 05-107- -00 Facility ID: 316758

Facility Name: DRY CREEK UNIT-65N88W Number: 22NENW

Qtrqtr: NENW Sec: 22 Twp: 5N Range: 88W Meridian: 6

Latitude: 40.379961 Longitude: -107.248449

CORRECTIVE ACTIONS:

1 CA# 198793

Corrective Action: Provide proper labeling

Date: 10/18/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Installed the proper label on the tank

ECMC Decision: _____

ECMC
Representative:

2 CA# 198794

Corrective Action: Remove stained material, dispose of properly and securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.

Date: 10/18/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Removed all stained oil from around the tank, tighten all fittings and confirmed all in good working condition

ECMC Decision:

ECMC
Representative:

3 CA# 198795

Corrective Action: Mark or remove anchor

Date: 10/18/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Marked anchor properly

ECMC Decision:

ECMC
Representative:

4 CA# 198796

Corrective Action: Provide proper bird protection or proof of protection

Date: 10/18/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Installed bird protection on heat treater

ECMC Decision:

ECMC
Representative:

5 CA# 198797

Corrective Action: Provide proper signage

Date: 10/18/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Replaced well sign with new one that has all required information

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Trudy Cundiff

Signed:

Title: Regulatory Compliance

Date: 10/17/2024 4:49:21 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403962170	FIR RESOLUTION SUBMITTED
403962186	Corrective Action Photos

Total Attach: 2 Files