

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403964924

Date Received:

10/21/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Heil, John

john.heil@state.co.us

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708904806

Inspection Date: 10/14/2024

FIR Submit Date: 10/14/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 432398

Location Name: Savage Number: RWF 23-25 County: _____

Qtrqtr: NESW Sec: 25 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.493826 Longitude: -107.837844

FACILITY - API Number: 05-045- -00 Facility ID: 432398

Facility Name: Savage Number: RWF 23-25

Qtrqtr: NESW Sec: 25 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.493826 Longitude: -107.837844

CORRECTIVE ACTIONS:

1 CA# 199667

Corrective Action: All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.

Date: 10/15/2024

Response: CA COMPLETED

Date of Completion: 10/14/2024

Operator Comment: A voicemail message was received from Inspector Smelser at 1:21 p.m. on 10/14/24 informing TEP of a leaking chemical containment tank located at the RWF 23-25-694 well pad. This information was immediately relayed to the Production Field Supervisor, Chuck Smith. Production personnel were in close proximity to the pad at the time of the notification and responded to the potential leak within minutes. Upon investigation, it was discovered that a loose pump fitting was causing a slow drip of fluid (corrosion inhibitor) to run down the injection line and

over the lip of the containment structure. The fitting was immediately tightened and the leak was stopped. Fluids that collected in the containment structure were evacuated, and the small volume of stained soils off the NE corner of the containment were also cleaned up on the same day (10/14/24). M. Gardner (TEP) spoke with W. Smelser (ECMC) on 10/14/24 and confirmed that the leak had been addressed. See attached photo.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: A voicemail message was received from Inspector Smelser at 1:21 p.m. on 10/14/24 informing TEP of a leaking chemical containment tank located at the RWF 23-25-694 well pad. This information was immediately relayed to the Production Field Supervisor, Chuck Smith. Production personnel were in close proximity to the pad at the time of the notification and responded to the potential leak within minutes. Upon investigation, it was discovered that a loose pump fitting was causing a slow drip of fluid (corrosion inhibitor) to run down the injection line and over the lip of the containment structure. The fitting was immediately tightened and the leak was stopped. Fluids that collected in the containment structure were evacuated, and the small volume of stained soils off the NE corner of the containment were also cleaned up on the same day (10/14/24). M. Gardner (TEP) spoke with W. Smelser (ECMC) on 10/14/24 and confirmed that the leak had been addressed. See attached photo.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 10/21/2024 4:12:01 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| | |
|-----------|---|
| 403964924 | FIR RESOLUTION SUBMITTED |
| 403965027 | Photo of chemical containment and soils |

Total Attach: 2 Files