

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403965363

Date Received:
10/22/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 7650
Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION
Address: 4900 COLLEGE BLVD
City: FARMINGTON State: NM Zip: 87402

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Stradling, Zach</u>		<u>zstradling@bmgdrilling.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001350
Inspection Date: 10/15/2024 FIR Submit Date: 10/17/2024 FIR Status: _____

Inspected Operator Information:

Company Name: BENSON-MONTIN-GREER DRILLING CORPORATION Company Number: 7650
Address: 4900 COLLEGE BLVD
City: FARMINGTON State: NM Zip: 87402

LOCATION - Location ID: 428734

Location Name: JACQUES 2-10-N33-10W Number: _____ County: _____
Qtrqr: SENE Sec: 4 Twp: 33N Range: 10W Meridian: N
Latitude: 37.135284 Longitude: -107.934125

FACILITY - API Number: 05-067-00 Facility ID: 428734

Facility Name: JACQUES 2-10-N33-10W Number: _____
Qtrqr: SENE Sec: 4 Twp: 33N Range: 10W Meridian: N
Latitude: 37.135284 Longitude: -107.934125

CORRECTIVE ACTIONS:

1 CA# 199840

Corrective Action: Comply with rule 1004, reclaim access point of location. Date: 11/01/2024

Response: CA COMPLETED Date of Completion: 10/21/2024

Operator Comment: Access has not been fully reclaimed to allow for rework to be completed as necessary. Access will be recontoured and decompacted once the slope and pad are stabilized.

ECMC Decision: _____

ECMC
Representative:

2 CA# 199841

Corrective Action: Comply with rule 1002f. Install or repair required BMPs.

Date: 10/24/2024

Response: CA COMPLETED

Date of Completion: 10/21/2024

Operator Comment: New erosion logs have been installed to repair the rill. The sediment deposition behind the erosion log has been removed to allow the BMP to function.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Zach Stradling

Signed:

Title: Vice President

Date: 10/22/2024 9:10:57 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403965363	FIR RESOLUTION SUBMITTED
403965436	BMP Repair Pic
403965438	BMP Repair Pic
403965439	BMP Repair Pic

Total Attach: 4 Files