

State of Colorado Energy & Carbon Management Commission



Document Number:
403968840

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:
10/24/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001242

Inspection Date: 09/18/2024

FIR Submit Date: 09/23/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306928

Location Name: BURKETT G.U.A-N34N8W Number: 1SWNE County: _____

Qtrqtr: SWNE Sec: 1 Twp: 34N Range: 8W Meridian: N

Latitude: 37.245801 Longitude: -107.692820

FACILITY - API Number: 05-067-00 Facility ID: 306928

Facility Name: BURKETT G.U.A-N34N8W Number: 1SWNE

Qtrqtr: SWNE Sec: 1 Twp: 34N Range: 8W Meridian: N

Latitude: 37.245801 Longitude: -107.692820

CORRECTIVE ACTIONS:

1 CA# 198975

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 906 and 1002.

Date: 09/28/2024

Response: CA COMPLETED

Date of Completion: 10/22/2024

Operator Comment: Stained soil cleaned up around wellhead.

ECMC Decision: _____

ECMC
Representative:

2 CA# 198976

Corrective Action: Comply with rule 1003.f, treat/remove weeds.

Date: 09/30/2024

Response: CA COMPLETED

Date of Completion: 10/22/2024

Operator Comment: Thistles removed from around location.

ECMC Decision:

ECMC
Representative:

3 CA# 198977

Corrective Action: Storm water BMPs and erosion controls (ie: ecofiber, straw mulch, erosion control blankets, etc.) need to be installed and maintained on portions of the project area sparse and bare soils until soils are stabilized with desirable perennial vegetation.

Date: _____

Response: CA COMPLETED

Date of Completion: 10/22/2024

Operator Comment: Drainage ditch installed at bottom of the cut slope and seeding of cut slope completed.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA complete. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: _____

Title: Permitting Specialist I

Date: 10/24/2024 10:40:20 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403968859	Burkett A2 CA Photos
-----------	----------------------

Total Attach: 1 Files