

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403969389

Date Received:  
10/24/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Laramie

cogccnotifications@laramie-energy.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 696206347

Inspection Date: 09/27/2024

FIR Submit Date: 10/04/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

### LOCATION - Location ID: 334426

Location Name: Gunderson Number: 29-09 Pad County: \_\_\_\_\_

Qtrqtr: SENE Sec: 29 Twp: 9S Range: 93W Meridian: 6

Latitude: 39.248406 Longitude: -107.788322

### FACILITY - API Number: 05-077- -00 Facility ID: 334426

Facility Name: Gunderson Number: 29-09 Pad

Qtrqtr: SENE Sec: 29 Twp: 9S Range: 93W Meridian: 6

Latitude: 39.248406 Longitude: -107.788322

### CORRECTIVE ACTIONS:

1 CA# 199339

Corrective Action: Comply with Rule 603.i

Date: 10/26/2024

Response: CA COMPLETED

Date of Completion: 10/18/2024

Operator Comment: Lines have been capped

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

3 CA# 199341

Corrective Action: Conduct additional reclamation in accordance with ECMC 1003 series rules. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district.

Date: 11/05/2024

Response: CA COMPLETED

Date of Completion: 10/18/2024

Operator  
Comment:

Slopes have been repaired

ECMC Decision:

ECMC  
Representative:

4 CA# 199342

Corrective Action: Comply with Rule 1002.f and install or repair required stormwater and erosion control BMPs in accordance with good engineering practices, in order to stabilize the slopes, and to minimize erosion, degradation and sediment transport. Ensure erosion controls are implemented to stabilize the seeded soils upon completion of additional reclamation work.

Date: 11/05/2024

Response: CA COMPLETED

Date of Completion: 10/18/2024

Operator  
Comment:

BMPS have been repaired.

ECMC Decision:

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lori Muhr

Signed:

Title: Regulatory Analyst

Date: 10/24/2024 1:41:02 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403969394	CA Photos
-----------	-----------

Total Attach: 1 Files