

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 10/24/2024



Location Entrance – Photo #04485



Location – Photo #04493

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 10/24/2024



Location – Photo #04486



Location – Photo #04489

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 10/24/2024



Location – Photo #04492



Wildlife Entry Hazard – Photo #04487

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 10/24/2024



Wildlife Entry Hazard – Photo #04488



Open-Ended Lines – Photo #04490

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 10/24/2024



Open-Ended Line – Photo #04491

Open-Ended Lines – Photo #04494

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NWSE

Location ID: 334795

Date: 10/24/2024



Insufficient Erosion Control on Lease Road – Photo #04495