

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2024

Submitted Date:

10/29/2024

Document Number:

713601574**FIELD INSPECTION FORM**Loc ID 307347 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 10758Name of Operator: OGRIS OPERATING LLCAddress: PO BOX 53467City: MIDLAND State: TX Zip: 79710**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	
WARD, GIENA		gward@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217522	WELL	PR	10/01/2021	CBM	071-06299	APACHE CANYON 3-9	RI

General Comment:

This is a reclamation inspection of the APACHE CANYON #04-11 location.
See attached photos and additional details within this report.

Location					
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:					
Corrective Action:				Date:	
Emergency Contact Number:					
Comment:				Date:	
Corrective Action:				Date:	
Good Housekeeping:					
Type					
Comment:					
Corrective Action:				Date:	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is an erosion gully along the cut slope that needs to be repaired and stabilized.
There is also some erosion along the access road.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 11/29/2024

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	292622	2059135	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601575	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6764835