

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403973731

Date Received:

10/30/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 55030

Name of Operator: MCCARTNEY ENGINEERING LLC

Address: 4251 KIPLING ST STE 575

City: WHEAT RIDGE State: CO Zip: 80033

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Krystal Heibel		krystal.heibel@state.co.us
Kyle Waggoner		kyle.waggoner@state.co.us
Jack McCartney		jack@mccartneyengineering.com
Dylan Edwardson		dylan.edwardson@state.co.us
Lisa McCartney		lisa@mccartneyengineering.com
Ron McCartney		ron@mccartneyengineering.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 709100386

Inspection Date: 09/10/2024

FIR Submit Date: 09/17/2024

FIR Status: _____

Inspected Operator Information:

Company Name: MCCARTNEY ENGINEERING LLC

Company Number: 55030

Address: 4251 KIPLING ST STE 575

City: WHEAT RIDGE State: CO Zip: 80033

LOCATION - Location ID: 317041

Location Name: WARREN*S J-62N49W Number: 11NWSW County: _____

Qtrqtr: NWS Sec: 11 Twp: 2N Range: 49W Meridian: 6

Latitude: 40.154066 Longitude: -102.830999

FACILITY - API Number: 05-121-00 Facility ID: 317041

Facility Name: WARREN*S J-62N49W Number: 11NWSW

Qtrqtr: NWS Sec: 11 Twp: 2N Range: 49W Meridian: 6

Latitude: 40.154066 Longitude: -102.830999

CORRECTIVE ACTIONS:

1 CA# 198803

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 07/26/2024

Response: CA COMPLETED

Date of Completion: 10/04/2024

Operator
Comment:

Holes filled.

ECMC Decision:

ECMC
Representative:

2 CA# 198804

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 07/26/2024

Response: CA COMPLETED

Date of Completion: 09/29/2024

Operator
Comment:

Removed stained soil.

ECMC Decision:

ECMC
Representative:

3 CA# 198805

Corrective Action: Comply with Rule 606.

Date: 07/16/2024

Response: CA COMPLETED

Date of Completion: 10/04/2024

Operator
Comment:

Plastic bag removed. Pipes left in place because removal would likely damage integrity of the berm.

ECMC Decision:

ECMC
Representative:

4 CA# 198806

Corrective Action: Comply with Rule 605.e. but having one correct and accurate sign on each tank.

Date: 12/15/2024

Response: CA COMPLETED

Date of Completion: 10/04/2024

Operator
Comment:

Painted over old sign.

ECMC Decision:

ECMC
Representative:

5 CA# 198807

Corrective Action: Install sign to comply with Rule 605.h.(3).

Date: 12/15/2024

Response: CA COMPLETED

Date of Completion: 10/22/2024

Operator
Comment:

Installed sign.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jack McCartney

Signed:

Title: Manager

Date: 10/30/2024 9:06:46 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403973731	FIR RESOLUTION SUBMITTED
403973760	Pictures

Total Attach: 2 Files